P301 PR-IWSYA 75 HP Primary

Report generated on: 9/22/2004 10:42 AM

Acquired: 9/22/2004 10:42 AM 1 xM = 3585 RPM Averages: 6

Figure of Merit = 360.

Maximum level: 108 (-3) VdB at 2xM on 1A in low range

RECOMMENDATIONS:

IMPORTANT: REPLACE MOTOR DRIVE END BEARING

DIAGNOSES:

SERIOUS MOTOR DRIVE END BEARING WEAR SLIGHT MOTOR DRIVE END BALL BEARING DEMOD

POSITION LEGEND:

POSITION 1 IS: MOTOR FREE END POSITION 2 IS: MOTOR COUPLED END POSITION 3 IS: PUMP COUPLED END

PI02 PR-KLY 60 HP Primary

Report generated on: 9/22/2004 1046 AM

Acquired: 9/22/2004 1046 AM 1xM = 3595 RPM Averages: 3

Figure of Merit = 607.

Maximum level: 122 (+7) VdB at 2xM on 3T in low range

RECOMMENDATIONS:

IMPORTANT: REPLACE MOTOR DRIVE END BEARING

DIAGNOSES:

SERIOUS MOTOR DRIVE END BEARING LOOSENESS SLIGHT MOTOR FREE END BEARING NOISE SLIGHT MOTOR DRIVE END BALL BEARING DEMOD

POSITION LEGEND:

POSITION 1 IS: MOTOR FREE END POSITION 2 IS: MOTOR COUPLED END POSITION 3 IS: PUMP COUPLED END

P515 SR-18A Primary

Report generated on: 9/24/2004 121 0 PM

Acquired: 9/24/2004 12:10 PM 1xM = 3585 RPM Averages: 9

Figure of Merit = 567.

Maximum Level: 111 (+6) VdB at CxM on 3R in low range

RECOMMENDATIONS:

IMPORTANT: REPLACE MOTOR FREE END BEARING IMPORTANT: REPLACE MOTOR DRIVE END BEARING

DIAGNOSES:

SERIOUS MOTOR DRIVE END BEARING LOOSENESS SERIOUS MOTOR FREE END BEARING LOOSENESS SLIGHT ANGULAR MISALIGNMENT

POSITION LEGEND:

POSITION 1 IS: MOTOR FREE END POSITION 2 IS: MOTOR COUPLED END POSITION 3 IS: PUMP COUPLED END

P-VC-28-A 5 HP Primary

Report generated on: 9/22/2004 03:51 PM

Acquired: 9/22/2004 0351 PM IxM = 1765 RPM Averages: 8

Figure of Merit = 230.

Maximum level: 100 (+17) VdB at 3xM on 2T in low range

RECOMMENDATIONS:

IMPORTANT: CHECK MOTOR BEARINGS FOR IMPROPER FIT.

DIAGNOSES:

SERIOUS MOTOR BEARING LOOSENESS

POSITION LEGEND:

POSITION 2 IS: MOTOR COUPLED END POSITION 3 IS: PUMP COUPLED END

P-VC-20-B 5 HP Secondary

Report generated on: 8/13/2004 09:40 AM

Acquired: 8/13/2004 09:40 AM I xM = 1 765 RPM Averages: 8

Figure of Merit = 310.

Maximum level: 122 (+23) VdB at 4.09xM on 2T in low range

RECOMMENDATIONS:

IMPORTANT: PERFORM MOTOR ELECTRICAL CHECKS AND MONITOR MOTOR FOR INCREASED VIBRATION

DIAGNOSES:

SERIOUS MOTOR WINDING FAULT OR ELECTRICAL PHASE IMBALANCE SLIGHT PUMP BALL BEARING WEAR SLIGHT MOTOR BEARING WEAR

POSITION LEGEND:

POSITION 2 IS: MOTOR COUPLED END POSITION 3 IS: PUMP COUPLED END